



ISSUED 24th January 2017

At Risk Cylinders

Worksafe published a Scuba Cylinder warning dated 22 December 2016, following a serious harm incident overseas. Also, included in this are cylinders which are manufactured from Alloy 6351-T6

Luxfer SP6498

Luxfer E6498

Luxfer SP8364

Wallter Kidde SP7042

Cylinders E 6576

Cylinders E6688

Cylinders E8107

Cylinders E8422

Luxfer DOT 3AL with a hydrostatic test date before 1989

CIG (Australia) AS 1777 with a hydrostatic test date before 1991

Luxfer originating in the UK marked with a hydrostatic test date before 1996

Walter Kidde DOT 3AL with a hydrostatic test date before 1990

Aluminium composite cylinders (hoop wrapped) marked: E7235 or E8023 or E8115

Cylinders can be identified by their cylinder markings by either locating the manufacture date typically marked mm yy or the DOT special permit (SP) or exemption (E) markings.

As the NZUA Scuba Cylinder Audit Program Test Certifier you are instructed with immediate effect in the interests of safety not to test or fill any cylinder that falls into the categories listed above.

A handwritten signature in blue ink, appearing to read "Steve Bishop".

Steve Bishop

Technical Manager/Advisor
Air Purity Ltd/NZ Underwater Association

The logo for Air Purity Ltd. The word "air" is in a light blue, lowercase, sans-serif font. The word "purity" is in a darker blue, lowercase, sans-serif font. The letters "LTD" are in a light blue, uppercase, sans-serif font.